



Release Notes

Seagate[®] Nytro[®] XP6302-8B4096 Application Acceleration Card

XP6302-8B4096

100829646 Release 16.1
November 2017

Revision History

Date	Description of Changes
November 2017	■ Patch release for Release 16.

© 2017, Seagate Technology LLC All rights reserved.

Publication number: 100829646, November 2017

Seagate, Seagate Technology and the Wave logo are registered trademarks of Seagate Technology LLC in the United States and/or other countries. Nytro, Nytro WarpDrive and SeaTools are either trademarks or registered trademarks of Seagate Technology LLC or one of its affiliated companies in the United States and/or other countries. All other trademarks or registered trademarks are the property of their respective owners.

No part of this publication may be reproduced in any form without written permission of Seagate Technology LLC. Call 877-PUB-TEK1(877-782-8351) to request permission.

When referring to drive capacity, one gigabyte, or GB, equals one billion bytes and one terabyte, or TB, equals one trillion bytes. Your computer's operating system may use a different standard of measurement and report a lower capacity. In addition, some of the listed capacity is used for formatting and other functions, and thus will not be available for data storage. Actual quantities will vary based on various factors, including file size, file format, features and application software. Actual data rates may vary depending on operating environment and other factors. The export or re-export of hardware or software containing encryption may be regulated by the U.S. Department of Commerce, Bureau of Industry and Security (for more information, visit www.bis.doc.gov), and controlled for import and use outside of the U.S. Seagate reserves the right to change, without notice, product offerings or specifications.

Seagate Technology Support Services

For Nytro Support, visit: <http://www.seagate.com/support/by-product/ssd-and-pcie-flash/>

For information regarding online support and services, visit: <http://www.seagate.com/contacts/>

Available services include:

- Presales & Technical support
- Global Support Services telephone numbers & business hours
- Authorized Service Centers

For information regarding Warranty Support, visit: <http://www.seagate.com/support/warranty-and-replacements/>

For information regarding data recovery services, visit:

<http://www.seagate.com/services-software/seagate-recovery-services/recover/>

For Seagate OEM and Distribution partner and Seagate reseller portal, visit: <http://www.seagate.com/partners>

Seagate Nytro XP6302-8B4096 Application Acceleration Card Release Notes

1 Defects Fixed Since Release 16

This Release Notes is for the patch release for Release 16 and lists the defect(s) fixed since release 16.

- In XP6302-8B4096 devices, an issue related to VMware was resolved in the Firmware. The updated Firmware version is 16.00.03.00.

Issue that was resolved:

Virtual Machines configured on the card stops responding due to memory leak in the Firmware, thus causing an 0x8808 error message to be detected in the vmkernel system log. The kernel is sending an illegal request to the drive when configured as a datastore. The card Firmware is working as designed and is now ignoring the illegal request.



Seagate Technology LLC

AMERICAS Seagate Technology LLC 10200 South De Anza Boulevard, Cupertino, California 95014, United States, 408-658-1000

ASIA/PACIFIC Seagate Singapore International Headquarters Pte. Ltd. 7000 Ang Mo Kio Avenue 5, Singapore 569877, 65-6485-3888

EUROPE, MIDDLE EAST AND AFRICA Seagate Technology SAS 16-18 rue du Dôme, 92100 Boulogne-Billancourt, France, 33 1-4186 10 00

Publication Number: 100829646

November 2017